

Precipitation Rate of Zirconia (Volumetric Method)




FIG. 1

Zirconia Precipitation vs. Time
KR 41B at Varying Concentrations
(volumetric Method)




FIG. 2

Precipitation Rate of Zirconia in Acetone
KR 41B at Varying Concentrations
(Mass Accumulation Method)




FIG. 3